



A1 Thermal Imaging Services

Contact : Glenn Burns
PO Box 2700 Taren Point
Sydney NSW 2229
P: 0403 650 633
E: info@a1service.com.au
W: www.a1service.com.au



A1 Thermal Imaging Services

Thermography Report

Prepared For:

Sample Report
Joe Bloggs

Sample Report



Visible Light Image

IR000024.IS2



8/28/2008 7:04:14 AM

Image Info

Background Temperature	22.0°C
Emissivity	0.95
Average Temperature	18.4°C
Image Range	15.0°C to 36.3°C
Image Time	8/28/2008 7:04:14 AM

Main Image Annotations

Location	Great Hall
Description	BD1A fuse 13-14 hot
Priority Rating	3
Next inspection	3 Months Yes 6 Months 12 Months



Visible Light Image


IR000025.IS2
8/28/2008 7:11:52 AM

Image Info

Background Temperature	22.0°C
Emissivity	0.95
Average Temperature	20.9°C
Image Range	16.7°C to 42.3°C
Image Time	8/28/2008 7:11:52 AM

Main Image Annotations

Location	Bio Room
Description	DB A10 fuse 11 very hot
Priority Rating	2
Next inspection	3 Months- Yes 6 Months 12 Months



IR000222.IS2

5/28/2009 11:06:45 AM

Image Info

Background Temperature	22.0°C
Emissivity	0.95
Average Temperature	28.1°C
Image Range	18.5°C to 40.1°C
Image Time	5/28/2009 11:06:45 AM

Main Image Annotations

Location	CP 2 H1
Description	Fuse 8 pool plant
Priority Rating	Low Medium - yes High
Next inspection	Within 12 Months